6) Measure the distance for your throw line Wall Soft Tip Steel Tip Dartboard The laser line should be 96" from the face of the dartboard The laser line should be 93¹/₄" from the face of the dartboard Adjust the angle of the laser head so Use a common household that the line appears the correct distance item, such as a broom handle or ruler, to make a Measure 96" or 931/4" 96" or 931/4" temporary line at the correct distance. Measure from each side of the dartboard to the Temporary line temporary line. Temporary line 7) Once your laser throw line is set, tighten the 2 screws next to ball to secure the Laser Line in place. 8) WARNING: AVOID DIRECT EYE EXPOSURE Turn the Laser Dart Line on and position the laser head until it is flush with your temporary line. 9) If your surface area is uneven, loosen either the left or right screw and place shims behind the housing of the Laser Dart Line until the Laser Dart Line is in the correct position. LASER DART LINE Item #37-0108 Power Adapter Order Form Mail To: Name Date **GLD Products** S84 W19093 Enterprise Drive Phone-Day Address Muskego, WI 53150 City Phone-Evening Email: gld@gldmfg.com State Zip Email www.gldproducts.com Order# Description **Unit Price** QTY **Amount** #42-9988 5v 500ma Positive Outer Adapter \$10.00 Subtotal Shipping will be added. If paid by check or money order, S/H call for quote **Method of Payment** 5.1% Waukesha, WI tax will apply (Subject to Change) TAX Check or Money Order Total Credit Card _Visa __Mastercard __Discover __American Express Card# Security Code # Billing Address Zip Code Exp. Date Signature____ **Shipping Address** Name Muskego, WI 53150 Address Phone Phone www.gldproducts.com City_ State Zip Ver.B